



U.S. Department
of Transportation

**Federal Motor Carrier
Safety Administration**

JAN 24 2014

1200 New Jersey Avenue, SE
Washington, DC 20590

Jose Guadalupe Morales
d/b/a Fletes Morales
Calle Quintana Roo, #1225
Ensenada, BN 22840
MEXICO

In reply, refer to:MC-ESB

USDOT Number: 683409X
MX Number: 316863

The motor carrier safety rating for JOSE GUADALUPE MORALES D/B/A FLETES MORALES is:

SATISFACTORY

This SATISFACTORY rating is the result of a compliance review and evaluation of the safety fitness of this carrier completed on December 12, 2013. A SATISFACTORY rating indicates that the company has adequate safety management controls in place at this time to ensure compliance with the safety fitness standard prescribed in 49 CFR § 385.5.

On September 4, 2012, JOSE GUADALUPE MORALES D/B/A FLETES MORALES was granted a certificate of registration for Provisional Operating Authority (Provisional Operating Authority) to participate in the U.S.-Mexico Cross-Border Long-Haul Pilot Program (Pilot Program) authorizing transportation in the United States beyond U.S. municipalities and commercial zones on the U.S.-Mexico border. Operations under the Provisional Operating Authority are subject to subpart B of Part 385 of Title 49 of the Code of Federal Regulations (49 CFR §§ 385.101 – 385.119) and the terms and conditions of the Pilot Program. You are reminded that while JOSE GUADALUPE MORALES D/B/A FLETES MORALES remains in the safety monitoring program operating under Provisional Operating Authority, the Federal Motor Carrier Safety Administration (FMCSA) will continue to monitor your operating procedures to ensure compliance with all applicable U.S. safety regulations and the specific requirements of the Pilot Program.

Additionally, should you commit one or more of the violations described in 49 CFR § 385.105, you may be subject to an additional compliance review or required to submit a written response demonstrating corrective action. Failure to respond within 30 days to an Agency demand for a written response demonstrating corrective action will result in a suspension of your Provisional Operating Authority for the Pilot Program and may also affect your ability to operate under any OP-2 authority in the commercial zone.

If you have any questions or require further information, please contact your servicing FMCSA office at 2297 Niels Bohr Court, Suite 204, San Diego, CA 92154 or by phone at (619) 710-8400.

If you have any questions or require further information, please contact your servicing FMCSA office at 2297 Niels Bohr Court, Suite 204, San Diego, CA 92154 or by phone at (619) 710-8400.

Sincerely,

A handwritten signature in black ink, appearing to read "Joseph P. DeLorenzo". The signature is fluid and cursive, with a long horizontal stroke at the end.

Joseph P. DeLorenzo
Director, Office of Enforcement and Compliance

cc: Process Agent
Sarah Holtzman
11950 Aviation Boulevard
Inglewood, CA 90304